


202303 新產品號碼釋放

煞車系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|----------|---------------|---------------------------------------|----------------------|--|-----------|
| 剎車片磨損指示標 | 1987473029001 | 987 612 676 01 | POR | ayman 3.4 R [987C] (EU) 243 kW | 2009 |
| 剎車片磨損指示標 | 1987473004000 | 34 35 6 757 896 | BMW | Z4 Coupe (E86) 3.0 si;Z4 Roadster (E85) 2.0 i | 2006 |
| 剎車片磨損指示標 | 1987473006001 | A 164 540 10 17;A 220 540 15 17 | MERCEDES-BENZ | E-CLASS (W211) E 500 4-matic (211.083);G-CLASS (W463) G 55 AMG (463.270, 463.271) | 2010 |
| 剎車片磨損指示標 | 1987473011851 | A 163 540 15 17;A 163 540 17 17 | MERCEDES-BENZ | M-CLASS (W163) ML 270 CDI (163.113);M- CLASS (W163) ML 320 (163.154) | 2003-2005 |
| 剎車片磨損指示標 | 1987473019000 | A 211 540 07 17;211 540 07 17 | MERCEDES-BENZ | CLS (C219) CLS 320 CDI;E-CLASS (W211) E 200 CDI (211.004) | 2004-2006 |
| 剎車片磨損指示標 | 1987473028000 | 34 35 6 773 008;34 35 6 789 502 | BMW | X5 (E70) 3.0 sd;X6 (E71, E72) xDrive 35 d | 2008-2009 |
| 剎車片磨損指示標 | 1987473036001 | A 639 540 14 17;2E0 906 206 G | MERCEDES- BENZ/VW | SPRINTER 3,5-t Bus (B906) 310 CDI (906.731, 906.733, 906.735);CRAFTER 30-35 Bus (2E_) 2.0 TDI | 2003-2010 |
| 剎車片磨損指示標 | 1987473047000 | 34 35 7 836 795 | BMW | Z4 Coupe (E86) 3.0 si;Z4 Roadster (E85) 3.0 si | 2006-2009 |
| 剎車片磨損指示標 | 1987473048000 | 34 35 7 836 969 | BMW | Z4 Coupe (E86) M;Z4 Roadster (E85) M | 2006-2008 |
| 剎車片磨損指示標 | 1987473058000 | 34 35 6 783 230; 34 35 6 789 329 | MINI | MINI (R56) Cooper;MINI CLUBMAN (R55) Cooper | 2006-2010 |
| 剎車片磨損指示標 | 1987473502000 | 34 35 6 789 444 | BMW | Z4 Roadster (E89) sDrive 23 I;Z4 Roadster (E89) sDrive 30 i | 2006-2010 |


202303 新產品號碼釋放

煞車系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|----------|---------------|----------------------------------|-----|--|-----------|
| 剎車片磨損指示標 | 1987473503000 | 34 35 6 789 446 | BMW | Z4 Roadster (E89) sDrive 23 i; Z4 Roadster (E89) sDrive 30 i | 2009-2010 |
| 剎車片磨損指示標 | 1987473505000 | 34 35 6 790 341 | BMW | X1 (E84) sDrive 18 d; X1 (E84) xDrive 20 d | 2009-2010 |
| 剎車片磨損指示標 | 1987473506000 | 34 35 6 775 850 | BMW | 7 (F01, F02, F03, F04) 730 d; 7 (F01, F02, F03, F04) 740 i, Li | 2008-2009 |
| 剎車片磨損指示標 | 1987473507000 | 34 35 6 775 858 | BMW | 7 (F01, F02, F03, F04) 730 d; 7 (F01, F02, F03, F04) 740 i, Li | 2008-2009 |
| 剎車片磨損指示標 | 1987473508000 | 34 35 6 791 961 | BMW | 5 Gran Turismo (F07) 520 d; 5 Gran Turismo (F07) 528 i | 2012-2017 |
| 剎車片磨損指示標 | 1987473509000 | 34 35 6 791 962 | BMW | 5 (F10) 518 d; 6 Convertible (F12) 640 d | 2011-2016 |
| 剎車片磨損指示標 | 1987473512000 | 34 35 6 792 571 | BMW | X5 (E70) M; X5 (F15, F85) M | 2013-2018 |
| 剎車片磨損指示標 | 1987473514000 | 34 35 6 792 560 | BMW | 1 (E81) 123 d; 1 (E87) 123 d | 2009-2011 |
| 剎車片磨損指示標 | 1987473516000 | 34 35 6 792 562 | BMW | X1 (E84) sDrive 16 d; X1 (E84) sDrive 18 d | 2012-2015 |
| 剎車片磨損指示標 | 1987473518000 | 34 35 6 792 566 | BMW | Z4 Roadster (E89) sDrive 18 i; 20 i; 23 i; 28 i | 2013-2016 |
| 剎車片磨損指示標 | 1987473519000 | 34 35 6 792 561 | BMW | 3 (E90) 320 d xDrive; 3 Coupe (E92) 320 d xDrive | 2010-2012 |
| 剎車片磨損指示標 | 1987473520000 | 34 35 6 792 567 | BMW | X5 (E70) xDrive 30 d; 35i; X5 (F15, F85) sDrive 25 d | 2015-2018 |
| 剎車片磨損指示標 | 1987473521000 | 34 35 6 792 569; 34 35 6 860 181 | BMW | X5 (E70) M 50 d; X5 (F15, F85) M 50 d | 2013-2018 |


202303 新產品號碼釋放

煞車系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|----------|---------------|---|-----------------------|---|-----------|
| 剎車片磨損指示標 | 1987474901002 | A 000 540 02 17; A 123 540 00 17 | MERCEDES-BENZ/PUCH | 123 Coupe (C123) 230 C (123.043);G-MODELL (W460) 230 GE (460.238, 460.239) | 1988-1995 |
| 剎車片磨損指示標 | 1987474910850 | 34 11 2 225 107;34 35 1 179 820 | BMW | 5 (E28) M5;5 (E34) 518 i | 1992-1995 |
| 剎車片磨損指示標 | 1987474941000 | 34 35 1 163 117 | BMW | 7 (E38) 750 i, iL | 1994-1998 |
| 剎車片磨損指示標 | 1987474956851 | 34 35 1 182 533 | BMW | 3 Compact (E36) 316 g;Z3 Coupe (E36) 2.8 i | 1996-2000 |
| 剎車片磨損指示標 | 1987474957851 | 34 35 2 227 385 | BMW | 3 (E36) M3 3.0;3 Convertible (E36) M3 3.2 | 1994-1995 |
| 剎車片磨損指示標 | 1987474960850 | 34 35 6 751 311 | BMW | 3 (E46) 325 xi;3 Convertible (E46) 330 Cd | 2001-2006 |
| 剎車片磨損指示標 | 1987474963851 | A 163 540 13 17;163 540 13 17 | MERCEDES-BENZ | M-CLASS (W163) ML 230 (163.136);M- CLASS (W163) ML 270 CDI (163.113) | 2003-2005 |
| 剎車片磨損指示標 | 1987474964851 | A 163 540 14 17;163 540 14 17 | MERCEDES-BENZ | M-CLASS (W163) ML 230 (163.136);M- CLASS (W163) ML 270 CDI (163.113) | 2001-2005 |
| 剎車片磨損指示標 | 1987474966003 | A 220 540 06 17;A 220 540 07 17 | MERCEDES-BENZ | C-CLASS (W203) C 180 (203.035);C- CLASS (W204) C 180 CDI (204.000) | 2000-2003 |
| 剎車片磨損指示標 | 1987474969851 | A 901 540 00 17/9015400017/ 2D0 919 351 | MERCEDES-BENZ/PUCH/VW | G-CLASS (W461) G 280 CDI (461.304, 461.346, 461.370, 461.334, 461.339,...;G-CLASS (W463) 200 GE (463.220) | 2010-2015 |
| 剎車片磨損指示標 | 1987473005000 | 34 35 6 763 667;34 35 6 768 597 | BMW | 5 Touring (E61) 520 d;520 I;523 I;525 d;525 d xDrive | 2005-2007 |


202303 新產品號碼釋放

煞車系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|----------|---------------|---------------------------------------|------------------------|---|-----------|
| 剎車片磨損指示標 | 1987473007001 | A 901 540 02 17;2D0 919 351 A | MERCEDES- BENZ/VW | SPRINTER 3-t Bus (B903) 308 CDI;SPRINTER 4-t Bus (B904) 411 CDI | 2000-2006 |
| 剎車片磨損指示標 | 1987473046000 | 34 35 2 282 935 | BMW | 5 (E60) M5;5 Touring (E61) M5 | 2004-2009 |
| 剎車片磨損指示標 | 1987473057000 | A 202 540 07 17;2025400717 | MERCEDES- BENZ/PUCH | G-CLASS (W461) G 280 CDI (461.304, 461.346, 461.370, 461.334, 461.339,...;G- MODELL (W463) 230 GE (463.224, 463.225) | 2000-2005 |
| 剎車片磨損指示標 | 1987473059000 | 34 35 6 783 772;34 35 6 789 330 | MINI | MINI (R56) Cooper;MINI CLUBMAN (R55) Cooper | 2006-2010 |
| 剎車片磨損指示標 | 1987473513000 | 34 35 6 792 559 | BMW | 1 (E81) 116 d;1 (E87) 116 d | 2010-2011 |
| 剎車片磨損指示標 | 1987473540850 | 34 35 6 792 563 | BMW | Z4 Roadster (E89) sDrive 18 I;20 I;23 I;28 i | 2013-2016 |
| 剎車片磨損指示標 | 1987474549000 | 34 35 6 791 963 | BMW | 5 Touring (F11) 518 d;520 d;520 d xDrive | 2010~ |
| 剎車片磨損指示標 | 1987473070001 | A 000 540 02 17; A 123 540 00 17 | MERCEDES- BENZ/PUCH | 123 Coupe (C123) 230 C (123.043);G- MODELL (W460) 230 GE (460.238, 460.239) | 2002~ |
| 剎車片磨損指示標 | 1987473030000 | 34 35 6 764 851;34 35 6 777 650 | BMW | 3 (E90) 320 d xDrive;3 Coupe (E92) 320 d xDrive | 2010~ |
| 剎車片磨損指示標 | 1987473008001 | A 210 540 11 17;210 540 11 17 | MERCEDES-BENZ | C-CLASS (W202) C 43 AMG (202.033);C- CLASS T-Model (S202) C 43 AMG (202.093) | 1997-2000 |
| 剎車片磨損指示標 | 1987473042000 | 34 35 1 165 729 | BMW | 7 (E38) 740 d;7 (E38) 750 i, iL | 1998~ |


202303 新產品號碼釋放

煞車系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|----------|---------------|---------------------------------------|---------------|--|-----------|
| 剎車片磨損指示標 | 1987473504000 | 34 35 6 790 340 | BMW | X1 (E84) sDrive 18 d;X1 (E84) sDrive 20 d | 2010~ |
| 剎車片磨損指示標 | 1987473510000 | 34 35 6 792 568 | BMW | X5 (E70) M;X5 (F15, F85) M | 2010~ |
| 剎車片磨損指示標 | 1987474904850 | 34 11 1 152 607;34 35 1 179 819 | BMW | 3 (E30) 316;5 (E28) 518 | 1988-1991 |
| 剎車片磨損指示標 | 1987474905850 | 34 35 1 153 964;34 35 9 058 889 | BMW | 3 (E30) 316;Z1 Roadster 2.5 | 1988-1991 |
| 剎車片磨損指示標 | 1987474942851 | 34 35 1 163 207 | BMW | 5 Touring (E39) 520 d;523 I;525 d;525 i | 2000-2003 |
| 剎車片磨損指示標 | 1987474952850 | 34 35 1 181 823 | BMW | 8 (E31) 840 Ci;840 I;850 Csi;850 Ci;850 i,Ci | 1991~ |
| 剎車片磨損指示標 | 1987474953850 | 34 35 1 181 825 | BMW | 8 (E31) 840 Ci;840 I;850 Csi;850 Ci;850 i,Ci | 1991~ |
| 剎車片磨損指示標 | 1987474554000 | A 231 905 00 14;231 905 00 14 | MERCEDES-BENZ | CLS (C257) AMG CLS 53 EQ Boost 4-matic+ (257.361);E-CLASS (W213) AMG E 53 EQ Boost 4-matic+ (213.061) | 2018~ |
| 剎車片前片 | 0986T18098HDU | 446512670 | Toyota | Toyota Corolla Altis 1.8/Yaris 1.5 | 2019 |
| 煞車盤前盤 | 09864790937XR | 4249 F6 | CIT | DS4 2.0 BlueHdi [B75] 133 kW | 2014-2015 |


202303 新產品號碼釋放

車身電子系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|--------|---------------|-------------------------|-----|-------------------|-----------|
| 電子-噴水泵 | 039202400P000 | 04L965567 | VWW | Tiguan Allspace | 2017-2020 |
| 電子-噴水泵 | 0986338402000 | 5N0965561A | VAG | A6,Golf VI,Touran | 2015 |
| 電子-噴水泵 | 0392023525000 | 64218840613 | BMW | 5-Serie | 2017 |
| 電子-噴水泵 | 039202410X000 | 11518600285, 7643947 | BMW | | |
| 電子-噴水泵 | 039202320K000 | A0005000686 | MB | A,B CLA | 2012-2018 |


柴油系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|-------|---------------|---------------|-----|--------|-----------|
| 徑向式油泵 | 0445010811390 | 03N 130 755 A | VWW | Tiguan | 2016-2020 |


汽油噴射系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|--------|---------------|------------------|-----|-------------|-----------|
| 油泵支架總成 | 0580314334FP2 | 5W7 919 051 A | VWW | Saveiro III | 2000-2005 |


起發電機

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|-----|---------------|------------------------------|-----|-----------|-----------|
| 發電機 | 1986A01050WGP | 03L903023M | VWW | Golf VII | 2012-2017 |
| 起動機 | 0001147422BS1 | A2769064400 | MB | C,E,GLC,S | 2013 |
| 起動機 | 0001340501EVF | | | | |
| 起動機 | 1986S00612GF2 | 12418570846 , 12418577010 | BMW | 1,3,X3,X5 | 2015-2018 |

2023.03

New available part numbers



BOSCH

202303 新產品號碼釋放



轉向系統

| 產品 | Bosch料號 | OE號 | 品牌 | 車型 | 車型年分 |
|---------|---------------|-----------------|-----|------------|-----------|
| 電動助力轉向機 | KS00001950001 | A2044602501 | MB | GLK-Klasse | 2008-2013 |
| 液壓助力轉向機 | KS00002301001 | 5010600209 | REN | | |
| 電動助力轉向機 | KS0000196643E | A4474602900 | MB | V-Klasse | 2014 |
| 液壓助力轉向機 | KS00002304001 | X52 417 200 001 | MTU | | |